

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE

No. 014

Date :31-03-2026

It is certified that an inspection team headed by Pavithra B S Sr. Analyst RDWSD (Name of Officers with designation) from RDWSD District Laboratory Bangalore (Name of Department/ Office) inspected **SADHU VASWANI INTERNATIONAL SCHOOL** Situated No. 348/1 & 2, Near Railway Under Pass, Bettahalasuru, Jalla Hobli, Yelahanka, Bangalore-562157 (Name & Address of the School) on 26-03-2026 and the basis of Water Test Report number 014 dated 30-03-2026 of RDWSD District Laboratory Certified that the **SADHU VASWANI INTERNATIONAL SCHOOL** Situated No. 348/1 & 2, Near Railway Under Pass, Bettahalasuru, Jalla Hobli, Yelahanka, Bangalore-562157 (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T Govt.

The above valid for a period of 30-03-2027

Signature with Seal

Executive Engineer
Rural Drinking Water
and Sanitation
Bangalore (Urban) Bangalore

Name :

Designation :

Executive Engineer

Name & Address of the Department: RDWSD Division

Bengaluru

To

SADHU VASWANI INTERNATIONAL SCHOOL
No. 348/1 & 2, Near Railway Under Pass,
Bettahalasuru, Jalla Hobli, Yelahanka,
Bangalore-562157.

